ENGINEERING CHANGE NOTICE DART AEROSPACE LTD

	DA	ART AER	ROSPACE LTD				MPP			
Pate: 10.02.02 Job No.:		V	ADR Yes/No: Y ADR			various	JEON#	EØN#: 10- 514		
duct No.: D412-742			Created By:	Approve		M	7		VI-7	
uct Name: Skidtube			Checked By: ◀¥	General	Manage	er Approval:				
Distribution Regd Resp. Initi	al / Date	r	Distribution		Reqd	Resp	Initia	I / Date		
Production Manager / Coord.			DQA / QA Coord.		N					
Production Document Control Y BC	·		QC Coordinator		Y	JM				
Purchasing Coord. Y CL			Customer Technical Sur	pport	Υ	DStw				
Production Engineering Coord. Y EC/DD			Marketing		Υ	sw				
			Customer Order Proces	sing	N	<u> </u>				
Reason for Change:										
Documents Affected:										
- D2500 Rev. H										
- D3499 Rev. C										
- DSI 9475 Rev. A										
- DSI 9482 Rev. A										
- DEO-D3391-H-1										
PARTS MUST COMPLY	•	х	PREVIOUS PARTS	SATISF	ACTO	RY []			
# Quality Assurance Actions	Reqd	Resp	1	Notes			С	omplet	8	
1 Notify Previous Customers	N		·							
2 Notify Eurocopter France	N					•				
3	╁			•						
3	1	L					1			
# Engineering Actions	Reqd	Resp		Notes			C	omplete	9	
4 Required Documents/Drawings Under Review	N								-,.0	
5 Update Master Document List (MDL)	Y	СР	ROV. M				10.0	2.02	<u>-yr</u>	
6 Update Product Compatability Matrix	N						<u> </u>			
Create Eurocopter Form (FEE)	N						10.0	<u>,</u>	10	
otify TC / FAA of Change	Y	CP		· · · · · · · · · · · · · · · · · · ·			10.0	400	<u>ur</u>	
A	<u> </u>			 			<u> </u>			
# Document Control Actions	Reqd	Resp		Notes			C	omplete	e 10	
10 Move Electronic Files	Y	KJ	. A		·		10.02	03	745	
11 Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ	DS1 9475 (ON RG	eaves	ONL	у	10.02	CO.	dKX.	
12 Update Controlled PDF Files	Υ	KJ	-			17	10.0		3944	
13 Update Document Record (DR)	Υ	KJ	634 Rw. K, 646 Row	.B,66	i Rov. E	374260	<u> 10.0</u>	2.03	34	
14 Update Product Development Summary	N		•			1 1				
15 Update QSI 021 and/or STC Approval List	N						10 00	h 7	-44-	
16 Update Parts / STC Database	Y		DSI 9475 kits				10.02		· Div	
17 Update / Verify ARC Database	Ä	ΚŢ	DSI 9475 kits (Q) CH	<u> </u>	<u> </u>		120%	. <u>.03</u> 2.02	(TIM)	
18 Create / Update Change Record Form / Item Card Database	Y	KJ KJ	DSI 9475 kits @ CH	GUD	1		118.8	2.0	5 1KD	
19 Create / Update PPP's 20 Update Document Control Database / Laminated Dwgs	Y	KJ	as req'd				11/2	The same	- '(')	
21 Update Grey Project / Electronic Binder PDF Files	Y	KJ					16.0	20.0	3.54	
22 Update D-Part/M-Drawing/DSI/DEO Master Binders	Ÿ	ĸJ				 	10.02	.03	松叶	
23	<u> </u>						10.00	02	(4)2-	
24									\Box	
Description / Action:		-								
tolerance changes to D3499 to prevent assembly problems			n 1/0 56029							
- DEO-D3391-H-1 removed LPS-3, this has already been implem	ented in	productio	n who swall							
- DSI 9482 should be added to D412-742-011/-013/-041/-042 kits	s in stock	, ————————————————————————————————————	V . V							
- DSI 9475 was created for a customer (was send to customer by	/ Dan), s	hould only	be sent to customers on a	as-needed	basis					
- D2500 Rev. H adds ASTM spec										
- Keep CHG numbers the same, considering that skids are alread	dy being	made and	shipped w/o LPS-3							
		$\lambda \lambda$	1							
	r	/ X I\	\							
		, ,,,,	1) \(\tau \)		,					
	Y	(// V \	11/2 \ 1/1							
	X	M/	(.#X \	Λ						
		M/	$\mathcal{X} \setminus \mathcal{X}$	\mathcal{M}						
		M)		M						
				M	<u></u>				_	